

Notes:

1. TXP-T40 Optional Modbus / Relay board must be spec'd in order to connect to a Remote Sensor Assembly.
2. Modbus RS-485 wiring must be a 2 wire twisted pair with shield. Shield should be landed on the "S" terminal at the T40 Modbus / Relay board.
3. This example shows the T40 connecting to two Remote Sensor Assemblies.
4. Power wiring for the Remote Sensor Assemblies is to be run in its own 2 wire jacket and not inside the Modbus RS-485 jacket otherwise signal degredation will occur.

MACURCO GAS DETECTION

Macurco Inc.
1504 West 51st Street
Sioux Falls, SD 57105
United States of America
1-877-367-7891

TracXP™ Industrial Gas Solutions by Macurco

Title: TXP-T40 Dual Remote
Rev.: 1.0
Date: 10/18/2023

All drawings are for reference only. Electrical diagrams / drawings must be reviewed and approved by a local governing authority prior to installation. Macurco makes no representation or warranty concerning wiring diagrams / drawings, and you are to rely solely on the recommendations and requirements of the local governing authority.